

SERVIZIO REVIZIONE MOTORE

ABS MITSUBISHI PAJERO

Oem part numbers MR407202, MR569728, MR977461,
MN116391, B2PAS407230355, 0M080712, 7F29044,
2C290415, 2L070867, 2L010711, 0J130485, 2L300227,
OK120774, 20040821

RITIRIAMO E SPEDIAMO IN TUTTA EUROPA

Revisione completa del motore: **ritiro del vostro motore con nostro corriere**, riavvolgimento indotto, sostituzione di spazzole, collettore, montaggio collaudo e consegna.

Il prezzo include anche il trasporto per il rientro del vostro motore che sarà riconsegnato all'indirizzo che ci indicherete.

Tempi di riparazione : circa 5/7 gg

REVISION SERVICE POWER STEERING PUMP MOTOR ABS MITSUBISHI PAJERO

OEM part numbers MR407202, MR569728, MR977461,
MN116391, B2PAS407230355, 0M080712, 7F29044,
2C290415, 2L070867, 2L010711, 0J130485, 2L300227,
0K120774, 20040821

WE WITHDRAW AND WE SHIP ALL OVER EUROPE

Full engine Revision: **withdrawal of your motor with our courier**, rewind armature, replacing brushes, collector, installation testing and delivery.

The price also includes transportation for the return of your engine that will be delivered to the address you booking.

Repair Times: 5/7 working days

